

S. NO	NAME & ADDRESS	FIRE SAFETY SYSTEMS PROVIDED IN THIS BUILDING	SUGGESTIONS	REMARKS
1.	REPCO BANK No. 55, 4 th Main Road, Adyar, Chennai – 20	First Aid Fire extinguisher in 7 no's provided.	<ol style="list-style-type: none"> Number of fire extinguishers provided has to be increased as per IS 2190. Down Comer system should be provided. Over head water tank capacity should be increased to 5000 liters. Obstruction in the side setback area should be cleared. 	Non Compliance of Fire Safety Norms.
2.	Door No. 43, Rajalakhsmi Palace, Gandhi Nagar, 1 st Main Road, Adyar, Chennai - 20	NIL	<ol style="list-style-type: none"> Fire extinguishers have to be provided as per IS 2190. Hose Reel System should be provided. Down Comer System should be provided. Over head water tank capacity should be increased to 5000 liters. 	Non Compliance of Fire Safety Norms.
3.	Ashok Kumar Guleeha No. 102, L.B. Road, Adyar, Chennai – 20	First Aid Fire Extinguisher – ABC – 4kg in four no's provided.	<ol style="list-style-type: none"> Hose Reel System should be provided. Down Comer System should be provided. Over head water tank capacity should be increased to 5000 liters. Obstruction in the side setback area should be cleared. 	Non Compliance of Fire Safety Norms.
4.	Santhosh Hospital No. 1, 7 th Avenue, Besant Nagar, Chennai – 90	<ol style="list-style-type: none"> Hose Reel System installed in all the floors. Automatic Smoke Detection system provided. Automatic Sprinkler system installed. Fire Extinguisher provided. 	<ol style="list-style-type: none"> Hospital Emergency Rescue Team should be formed. Obstruction in the side setback area should be cleared. One Ramp should be provided. Exit Signage's should be provided. Suitable Fire Extinguisher's has to be provided at suitable area. 	Non Compliance of Fire Safety Norms.
5.	Janaki Apartment Plot no. 74, D.No. 204, Sardar Patel Road, Adyar, Chennai – 20	NIL	<ol style="list-style-type: none"> Fire extinguisher should be provided as per IS 2190. Hose Reel system should be provided at all floors. Fire alarm system should be provided. Obstruction in the side setback area should be cleared. 	Non Compliance of Fire Safety Norms.
6.	Ramco Systems D.No. 64, Sardar Patel Road, Adyar, Chennai – 20	<ol style="list-style-type: none"> Wet Riser System provided. Down Comer System provided Manual Call Point provided Automatic Smoke Detection System provided. Automatic Sprinkler System provided. First Aid Fire Extinguisher's provided. Public Addressed system provided. Pumps provided: <ol style="list-style-type: none"> Electrical Pump – 100 HP Diesel Pump – 90 HP Jockey Pump – 20 HP 	<ol style="list-style-type: none"> Necessary 7 meters side setback area should be provided. 	Non Compliance of Fire Safety Norms.

7.	Suruthi Apartments D.No. 21, Plot No. 135, 2 nd Main Road, Gandhi Nagar, Adyar, Chennai – 20	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers have to be provided as per IS. 2. Down Comer System should be provided. 3. Hose Reel System should be provided. 4. Side setback obstructions should be removed. 5. Over head water tank capacity should be increased to 5000 liters. 	Non Compliance Of Fire Safety Norms.
8.	Keerthi Vasan No. 78, Sardar Patel Road, Adyar, Chennai – 20	First Aid Fire Extinguisher 4 no's provided.	<ol style="list-style-type: none"> 1. Down comer system should be provided. 2. Hose Reel system should be provided. 3. Terrace tank capacity of 5000 liters should be provided. 4. Fire Alarm system should be provided. 5. Side setback obstructions should be removed. 6. Fire Pump Capacity of 900 LPM should be provided at terrace level. 	Non Compliance of Fire Safety Norms.
9.	Dev Apartments No. 5, Kasthuri Bhai Nagar, 1 st Main Road Adyar, Chennai – 20	First Aid Fire Extinguishers 17 no's provided.	<ol style="list-style-type: none"> 1. Number of fire extinguishers provided has to be increased as per IS 2190. 2. Hose Reel system should be provided. 3. Down Comer system should be provided. 4. Over head water tank capacity should be increased to 5000 liters. 5. Side setback obstructions should be removed. 	Non Compliance of Fire Safety Norms.
10.	D.No. 6, 1 st main road, Kasthuri Bhai Nagar, Adyar, Chennai – 20	First Aid Fire Extinguishers ABC 4kg type– 7 no's, Co2 – 4.5kg type – 4 no's provided.	<ol style="list-style-type: none"> 1. Fire extinguishers have to be provided as per IS 2. Hose Reel system should be provided. 3. Down Comer should be provided. 4. Over head water tank capacity should be increased to 5000 liters. 5. Fire Pump Capacity of 900 LPM should be provided at terrace level. 6. Side setback obstructions should be removed. 	Non Compliance Of Fire Safety Norms.
11.	Ceebross Arcade No. 1, Illrd Cross street, Kasthuri Bhai Nagar, Adayar, Chennai – 20	First Aid Fire Extinguishers 5 no's provided.	<ol style="list-style-type: none"> 1. Number of fire extinguishers provided has to be increased as per IS 2190. 2. Hose Reel system should be provided 3. Down Comer System should be provided 4. Over head water tank capacity should be increased to 5000 liters. 	Non Compliance of Fire Safety Norms.
12.	No. 34/36, 7 th Avenue, Besant Nagar, Chennai – 90	First Aid Fire Extinguishers installed at commercial area - 3 no's (ABC type 4kg)	<ol style="list-style-type: none"> 1. Number of fire extinguishers provided has to be increased as per IS 2190. 2. Hose Reel system should be provided. 3. Down Comer System should be provided. 4. Fire Pump Capacity of 900 LPM should be provided at terrace level. 	Non Compliance Of Fire Safety Norms.
13.	No. 32/34 Coastal Road, Besant Nagar, Chennai – 90.	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers have to be provided as per IS 2. Hose Reel system should be provided. 3. Over head water tank capacity should be increased to 5000 liters. 4. Side setback obstructions should be removed. 	Non Compliance of Fire Safety Norms.

14.	Sea Port Apartments No. 41/70, Beach Road, Kalakshetra Colony, Besant Nagar, Chennai – 90	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers have to be provided as per IS 2. Hose Reel system should be provided. 3. Over head water tank capacity should be increased to 5000 liters. 4. Side setback area obstructions should be removed. 5. Alternative staircase should be provided. 	Non Compliance Of Fire Safety Norms.
15.	Gokul Arcade No. 2, Sardar Patel Road, Adyar, Chennai – 20	First Aid Fire Extinguisher provided in few quantities.	<ol style="list-style-type: none"> 1. Fire Extinguisher should be installed as per IS 2190. 2. Wet riser system should be provided. 3. Hose Reel system should be provided. 4. Fire alarm system should be provided. 5. Side setback area at northern side and southern side setback area violation should be cleared. 6. Manual Call Points system should be provided. 7. Over head water tank capacity should be increased to 5000 liters. 8. Pumps: Electrical – 2280 lpm, Diesel – 2280 lpm, Jockey – 180 lpm 	Non Compliance Of Fire Safety Norms.
16.	No. 37/87, 1 st Main Road, Gandhi Nagar, Adyar, Chennai – 600 020.	First Aid Fire Extinguishers 12 no's provided.	<ol style="list-style-type: none"> 1. Down Comer system should be provided. 2. Hose Reel system should be provided. 3. Obstruction in the side setback area should be cleared. 	Non Compliance of Fire Safety Norms.
17.	Hotel Shreelekha Regency Pvt Ltd No. 564, Anna Salai, Teynampet, Chennai – 18	Fire Extinguishers – Co2 – 10 no's DCP 4.5kg – 2 no's provided.	All Fire Fighting systems are available.	
18.	G.R. Ganesh No. 23, Padmanathan Road and Lioyds Road, Gopalapuram, Chennai – 86		<ol style="list-style-type: none"> 1. Down Comer system with Hose Reel assembly should be installed. 2. Fire Extinguishers have to be provided as per IS 2190. 	Non Compliance of Fire Safety Norms.
19.	Mr. K. Ramaniyam & Others No. 16, Centoph Road, 1 st Street, Chennai – 18		<ol style="list-style-type: none"> 1. Down Comer system with Hose Reel assembly should be installed. 2. Fire Extinguishers have to be provided as per IS 2190. 	Non Compliance of Fire Safety Norms.
20.	The Sarala Chorida & others No. 171, Avvai Shanmugam Salai, Gopalapuram, Chennai – 86	<ol style="list-style-type: none"> 1. Manual Call Points provided. 2. Smoke Detection system provided. 3. Fire extinguishers ABC –type 6kg - 6 no's, Co2 type – 2kg – 6 no's provided. 	<ol style="list-style-type: none"> 1. Wet riser system with hose reel assembly should be provided. 2. One electrical and Diesel Pump capacity of 2280 LPM and a jockey pump with capacity of 180 LPM should be provided. 	Non Compliance of Fire Safety Norms.
21.	M.A. Jacob No. 11, Damodran Street, Gopalapuram, Chennai – 86	NIL	<ol style="list-style-type: none"> 1. Wet riser system with hose reel assembly should be provided. 2. One electrical and Diesel Pump capacity of 2280 lpm and a jockey pump with capacity of 180 lpm should be provided. 3. Sprinkler system should be installed. 4. Smoke Detector with MCP should be installed. 	Non Compliance of Fire Safety Norms.

22.	Ashok Kumar Goel Geetha Bhavan Trust, No. 334, Avvai Shanmugam Salai, Gopalapuram, Chennai - 86	1. Hose Reel system with Hydrant provided. 2. Fire extinguishers ABC type – 4kg – 13 no's provided.	1. Wet riser system with hose reel assembly should be provided. 2. One electrical and Diesel Pump capacity of 2280 lpm and a jockey pump with capacity of 180 lpm should be provided. 3. Smoke Detector with MCP should be installed.	Non Compliance of Fire Safety Norms.
23.	Ram Chand No. 7, Kasturi Rangan Road, Gopalapuram, Chennai – 86	NIL	1. Down Comer system with Hose Reel assembly should be provided. 2. MCP should be provided.	Non Compliance of Fire Safety Norms.
24.	Meridian Appearels Ltd No. 121/3, Manickam Avenue, T.T.K. Road, Alwarpet, Chennai – 18	Fire extinguishers DCP type – 2kg – in 10 no's provided.	1. Wet riser system with hose reel assembly should be provided. 2. One electrical and Diesel Pump capacity of 2280 lpm and a jockey pump with capacity of 180 lpm should be provided. 3. Sprinkler system should be installed. 4. Smoke Detector with MCP should be installed.	Non Compliance of Fire Safety Norms.
25.	M.V. Diabetis & Specialties D.No. 35, Corram Smith Road, Gopalapuram, Chennai - 86	1. Fire Hydrant System provided. 2. Fire Extinguisher in 45 no's provided.	1. Sprinkler system should be installed. 2. One electrical and Diesel Pump capacity of 2280 lpm and a jockey pump with capacity of 180 lpm should be provided.	Non Compliance of Fire Safety Norms.
26.	Sampath Kumar No. 74, Thiruvalluvar street, Teynampet, Chennai – 18	NIL	1. Hose Reel assembly should be provided. 2. One Electrical Pump capacity of 450 lpm should be provided at near OHT.	Non Compliance of Fire Safety Norms.
27.	Sudharshan Building No. 86, Chaimers Road, Teynampet, Chennai – 18	NIL	1. Wet riser system with hose reel assembly should be provided. 2. One electrical and Diesel Pump capacity of 2280 lpm and a jockey pump with capacity of 180 lpm should be provided. 3. Sprinkler system should be installed. 4. Smoke Detector with MCP should be installed.	Non Compliance of Fire Safety Norms.
28.	Keshav Sign D.No. 14/50, K.B. Dasan Road, Alwarpet, Chennai - 18	NIL	Hose Reel assembly with Down comer system should be provided.	Non Compliance of Fire Safety Norms.
29.	Venkatraman No. 21, 3 rd Street, Abiramapuram, Chennai – 18	NIL	Hose Reel assembly with Down comer system should be provided.	Non Compliance of Fire Safety Norms.
30.	Karthik No. 310, T.T.K. Road, Alwarpet, Chennai – 18	1. Down Comer with Hose Reel system provided. 2. Smoke Detector System provided. 3. Sprinkler system provided only at Basement floor. 4. Fire extinguishers of ABC type – 2kg in 2 no's, 6kg in 1no provided.	1. Wet riser system with hose reel assembly should be provided. 2. One electrical and Diesel Pump capacity of 2280 lpm and a jockey pump with capacity of 180 lpm should be provided. 3. Sprinkler system should be installed at all floors. 4. Smoke Detector with MCP should be installed.	Non Compliance of Fire Safety Norms.

31.	Jaiveer Agarwals & others No. 19, Cathedral Road, Gopalapuram, Chennai – 86	1. Wet Riser system provided 2. Fire Extinguishers of ABC 6kg and Co2 – 4.5kg provided.	1. Sprinkler system should be installed. 2. Manual Call Point system should be installed.	Non Compliance of Fire Safety Norms.
32.	Kalarani No. 21, C.V. Raman Salai, Alwarpet, Chennai – 18	Fire extinguishers of DCP type 5kg in 3nos provided.	1. Down Comer system with Hose Reel assembly should be provided. 2. Fire extinguishers have to be provided as per IS 2190.	Non Compliance of Fire Safety Norms.
33.	S.R. Selvaraj No. 231, Murrys Gate Road, TTK Road, Alwarpet, Chennai – 18	NIL	1. Down Comer system with Hose Reel assembly should be provided. 2. Fire extinguishers have to be provided as per IS2190.	Non Compliance of Fire Safety Norms.
34.	K.L.V. Rama Rao No. 124, G.N. Chetty Road, T.Nagar, Chennai – 17.	NIL	1. Fire Extinguisher should be provided at all floors. 2. Hose Reel system should be provided at all floors. 3. Down Comer system should be provided. 4. Manual Call Point should be provided at all floors.	Non Compliance of Fire Safety Norms.
35.	No. 11/6, Thirumurthy Street, T. Ngar, Chennai – 17	NIL	1. Fire Extinguishers should be provided at all floors. 2. Hose Reel system should be provided at all floors. 3. Obstruction in the side setback area should be cleared.	Non Compliance of Fire Safety Norms.
36.	No. 133, Thyagaraya Road, T.Ngar, Chennai – 17	1. Manual Call Points provided. 2. First Aid Fire extinguishers provided. 3. Signage's provided. 4. Public Addressed system provided.	1. Additional Fire Extinguisher system should be provided as per IS 2190 2. Wet Riser system should be provided. 3. Yard Hydrant System should be provided. 4. Sprinkler system should be provided. 5. UG water tank capacity has to be increased up to 75000 liters. 6. Pumps: One Electrical pump capacity of 2280 lpm, Jockey pump capacity of 180 lpm, Diesel Pump capacity of 2280 lpm should be provided.	Non Compliance of Fire Safety Norms.
37.	Lalitha Lakshmi No. 41, Thirumalai Pillai Road, T. Ngar, Chennai – 17	1. Wet Riser system provided. 2. Down Comer System provided, 3. Manual Call Points provided. 4. Automatic Sprinkler system provided. 5. Hose Reel system provided.	Setback area should be kept free from all side of the building.	Non Compliance of Fire Safety Norms.
38.	A.N. Sulai Maan No. 8, Dr.B.N. Road, T. Nagar, Chennai – 17		1. Fire Extinguisher should be provided at all floors. 2. Hose Reel system should be provided at all floors. 3. Down Comer system should be provided. 4. Manual Call Point should be provided at all floors. 5. UG water tank capacity has to be increased up to 75000 liters. 6. Pumps: one electrical pump 2280 lpm and one Jockey pump 180 lpm and one Diesel Pump 2280 lpm should be provided.	Non Compliance of Fire Safety Norms.
39.	Kiran Reddy No. 76, Bazullah Road, T.Nagar, Chennai – 17	Fire extinguishers of ABC type 3 nos provided.	1. Additional Fire Extinguisher system should be provided as per IS 2190. 2. Wet Riser system should be provided. 3. Yard Hydrant System should be provided. 4. Sprinkler system should be provided.	Non Compliance of Fire Safety Norms.

			<ul style="list-style-type: none"> 5. UG water tank capacity has to be increased up to 100000 liters 6. Pumps: Electrical pump 2280 lpm, Jockey pump 180 lpm, Diesel Pump 2280 lpm should be provided. 	
40.	V. Sudhakar No. 95, G.N. Chetty Road, T. Nagar, Chennai – 17	Fire extinguishers of ABC type 2kg – 6 no's provided	<ul style="list-style-type: none"> 1. Additional Fire Extinguisher system should be provided as per IS 2190. 2. Wet Riser system should be provided. 3. Yard Hydrant System should be provided. 4. Sprinkler system should be provided. 5. UG water tank capacity has to be increased up to 50000 liters. 6. Pump: An Electrical pump 2280 LPM, a Jockey pump 180 LPM, Diesel Pump 2280 LPM should be provided. 	Non Compliance of Fire Safety Norms.
41.	S. Gayanchand No. 13, Dr.NairRoad, T.Nagar, Chennai – 17	Fire extinguishers of ABC type 5kg – 4 no's provided	<ul style="list-style-type: none"> 1. Additional Fire Extinguisher system should be provided as per IS 2190. 2. Wet Riser system should be provided. 3. Yard Hydrant System should be provided. 4. Sprinkler system should be provided. 5. UG water tank capacity has to be increased up to 75000 liters. 6. Pump: An Electrical pump 2280 LPM, a Jockey pump 180 LPM, Diesel Pump 2280 LPM should be provided. 	Non Compliance of Fire Safety Norms.
42.	B. Gnana Sekaran No.11, Sarangapani Street, T. Nagar, Chennai – 17	<ul style="list-style-type: none"> 1. Down Comer with Hose Reel system provided. 2. Manual Call Points provided. 3. Fire extinguishers provided. 4. Public Address System provided (During inspection above said fire safety systems were not in working condition) 	<ul style="list-style-type: none"> 1. Additional Fire Extinguisher system should be provided. 2. Wet Riser system should be provided. 3. Yard Hydrant System Should be provided. 4. Sprinkler system should be provided. 5. UG water tank capacity has to be increased up to 75000 liters. 6. Pump: An Electrical pump 2280 LPM, a Jockey pump 180 LPM, Diesel Pump 2280 LPM should be provided. 	Fire safety systems provided has to be kept in proper working condition.
43.	No. 74, Sidco Industrial Road, Guindy, Chennai – 32	<ul style="list-style-type: none"> 1. Manual call points provided. 2. Smoke Detector system installed. 3. Fire fighting extinguisher's ABC 2kg – 45 no's, ABC 5kg – 7 no's, CO2 – 2kg – 2 no's provided. 	<ul style="list-style-type: none"> 1. Wet Riser system should be provided. 2. Yard Hydrant System should be provided. 3. Sprinkler system should be provided. 4. UG water tank capacity has to be increased up to 75000 liters. 5. Pump: An Electrical pump 2280 LPM, a Jockey pump 180 LPM, Diesel Pump 2280 LPM should be provided. 	Non Compliance of Fire Safety Norms.
44.	K.V. Suseela No. 25/6, Five Furlong Road, Guindy, Chennai – 79	NIL	<ul style="list-style-type: none"> 1. Hose Reel System should be provided. 2. Down Comer System should be provided. 3. Fire extinguishers have to be provided as per IS 2190. 4. Side setback area obstruction should be cleared. 	Non Compliance of Fire Safety Norms.
45.	K. Shivaram No. 25/7, Guindy Race Course Road, Five Furlong Road, Chennai – 32	NIL	<ul style="list-style-type: none"> 1. Hose Reel System should be provided. 2. Down Comer System should be provided. 3. Fire extinguishers have to be provided as per IS 2190. 4. Side setback area obstruction should be cleared. 	Non Compliance of Fire Safety Norms.
46.	Maheswaran No. 50, Anantha Roshini	NIL	<ul style="list-style-type: none"> 1. Hose Reel System should be provided. 2. Down Comer System should be provided. 	Non Compliance of Fire Safety Norms.

	Apartment, 1 st Main Road, Nanganallur, Chennai – 61		3. Fire extinguishers have to be provided as per IS 2190. 4. Side setback area obstruction should be cleared.	Norms.
47.	Uppili Balaji No. 50, 1 st Main Road, Nanganallur, Chennai – 61			
48.	Vimala Nagarajan No. 50, 1 st Main Road, Anantha Roshini Apartments Nanganallur, Chennai – 61			
49.	R. Viswanathan No. 52, Anantha Roshini Apartments, 1 st Main Road, Nanganallur, Chennai – 61			
50.	Ayya Tower No. 66, 67, 100 Ft Taramani Link Road, Seethapathy Nagar, Velachery, Chennai - 42	NIL	1. Hose Reel system should be provided. 2. Side setback area obstruction should be removed. 3. Fire extinguishers have to be provided as per IS 2190.	Non Compliance of Fire Safety Norms.
51.	No. 3D, Velachery Main Road, Velachery, Chennai – 42	NIL	1. Fire extinguishers have to be provided as per IS 2190. 2. Down Comer system with hose reel assembly should be provided. 3. Side setback area obstruction should be cleared.	Non Compliance of Fire Safety Norms.
52.	Ayya Arcade No. 23, V.G.P. Baby Nagar, Velachery, Chennai – 42	NIL	1. Hose Reel system should be provided. 2. Side setback area obstruction should be removed. 3. Fire extinguishers have to be provided as per IS 2190.	Non Compliance of Fire Safety Norms.
53.	Pet Houses in IV Floor, D.No. 33D, Velachery Main Road, Velachery, Chennai - 42		1. Hose Reel system should be provided. 2. Side setback area obstruction should be removed. 3. Fire extinguishers have to be provided as per IS 2190.	Non Compliance of Fire Safety Norms.
54.	No. 51, 10 th Avenue, Ashok Nagar, Chennai – 83	1. Fire extinguisher ABC type 10 kg provided. 2. Hose Reel system provided	1. Hose Reel system should be provided. 2. Side setback area obstruction should be cleared. 3. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors.	Non Compliance of Fire Safety Norms.
55.	No. 11, 11 th Avenue, Ashok Nagar, Chennai – 83	NIL	1. Hose Reel system should be provided. 2. Side setback area obstruction should be cleared. 3. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors.	Non Compliance of Fire Safety Norms.
56.	No. 94, 21 st Avenue, Ashok Nagar, Chennai – 83	NIL	1. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Side setback area obstruction should be kept free from all sides.	Non Compliance of Fire Safety Norms.
57.	No. 12, 1 st Avenue, Ashok Nagar, Chennai – 83	NIL	1. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors. 1. Hose Reel system should be provided. 2. Side setback area obstruction should be removed.	Non Compliance of Fire Safety Norms.

58.	K.M. Iqbal Amarnath Building, No. 172, Arcot Road, Vadapalani, Chennai – 26	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Hose Reel system should be provided. 3. Down Comer system should be provided. 4. Automatic Sprinkler system should be provided. 5. Manual call Points have to be provided. 6. Side setback area obstruction should be kept free from all sides. 	Non Compliance of Fire Safety Norms.
59.	Venkatraman Sai Vignesh Apartments, 19 th Avenue, Ashok Nagar, Chennai – 83	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Hose Reel system should be installed. 3. Side setback area obstruction should be kept free from all sides. 	Non Compliance of Fire Safety Norms.
60.	Ponmani Vairamuthu No. 8, Ganga Nagar, 2 nd Cross Street, Kodambakkam, Chennai – 24	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 6kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Hose Reel system should be installed. 3. Side setback area obstruction should be kept free from all sides. 	Non Compliance of Fire Safety Norms.
61.	J. Mlathy Jeevanantham No. 366, Arcot Road, Vadapalani, Chennai – 26	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 6kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Hose Reel system should be provided. 3. Down Comer system should be provided. 4. Manual call points should be provided. 5. Necessary Side setback area from all sides. 	Non Compliance of Fire Safety Norms.
62.	Aspni Inn No. 77, Jawaharlal Nehru Road, Vadapalani, Chennai – 26	<ol style="list-style-type: none"> 1. Down Comer System provided. 2. Hose Reel system provided. 3. First Aid Fire Extinguishers Co2 9kg in 4 no's and ABC 6kg in 7 no's provided. 	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. MCP should be provided at all floors of the building 3. Obstruction in the side setback area should be removed. 	Non Compliance of Fire Safety Norms.
63.	Rm. Mariappan D.No. 1, 4 th Street, Postal Colony, West Mambalam, Chennai – 33	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floors. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Hose Reel system should be provided. 3. Obstruction in the side setback area should be removed. 	Non Compliance of Fire Safety Norms.
64.	No. 25, 1 st main road, United India Colony, Kodambakkam, Chennai – 24	<ol style="list-style-type: none"> 1. Down Comer system provided. 2. First Aid Fire Extinguishers of ABC – 6kg type in 4 no's provided. 	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 2 no's has to be maintained at every floor. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Wet riser with Hose Reel assembly should be provided. 3. Automatic smoke Detection and Alarm system should be provided. 4. All backup system should be working condition. 5. Obstruction from side setback area should be removed. 	Non Compliance of Fire Safety Norms.

65.	Sultan Mohideen No. 2/2, Station Road, West Mambalam, Chennai – 33	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 3no's has to be maintained at every floor. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Wet riser with Hose Reel assembly should be provided. 3. Automatic smoke Detection & Alarm system should be provided. 4. All backup system should be working condition. 5. Obstruction from side setback area should be removed. 	Non Compliance of Fire Safety Norms.
66.	V.R. Neduncheliyan No. 5, 3 rd Floor,, 102-A, Rangarajapuram, Kodambakkam, Chennai – 24	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 3no's has to be maintained at every floor. Fire extinguishers have to be provided as per IS 2190 for every floors. 2. Wet riser with Hose Reel assembly should be provided. 3. Automatic smoke Detection & Alarm system should be provided. 4. Obstruction from side setback area should be removed. 	Non Compliance of Fire Safety Norms.
67.	No. 19, Lake View Road, West Mambalam, Chennai – 33	NIL	<ol style="list-style-type: none"> 1. Fire extinguishers of ABC type – 10kg in 3no's has to be maintained at every floor. Fire extinguishers have to be provided as per IS 2190 for every floor. 2. Hose Reel assembly should be provided. 3. Automatic smoke Detection & Alarm system should be provided. 4. Obstruction from side setback area should be removed. 	Non Compliance of Fire Safety Norms.
68.	Nandha Plats, No.15,16, Karaneeshwarar Koil Street, Saidapet, Chennai – 15.	Fire extinguishers of DCP 5 Kg type in single no' and CO ₂ 2.5 Kg type in single no provided.	<ol style="list-style-type: none"> 1. Down comer system with Hose reel assembly should be installed. 2. Fire extinguishers have to be provided as per IS 2190 for every floor. 3. MCP and Smoke Detector should be installed at the Bank. 4. 900 LPM capacity of Pump should be provided at terrace level. 	Non Compliance of Fire Safety Norms.
69.	Temple Tower, No.672, Anna Salai, Nandanam, Chennai – 35.	Fire extinguishers of DCP 5 Kg type in 25 no's and CO ₂ 4.5 Kg type in 5 no's and ABC 5 Kg type in 5 No's provided.	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Yard Hydrant should be provided. 3. Two electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided 4. Manual Call Points and Automatic smoke Detection and alarm system should be provided. 5. Sprinkler system should be provided at all floors. 	Non Compliance of Fire Safety Norms.
70.	Regency House, No.341/250, Anna Salai, Teynampet, Chennai – 06	NIL	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Pumps: One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided. 3. Manual Call Points& Automatic Smoke Detection and 	Non Compliance of Fire Safety Norms.

			alarm system should be provided. 4. Fire extinguishers have to be provided as per IS 2190 for every floors.	
71.	K.G. Lakshmi Narayanan, No.22/12, III rd Cross Street, (Alpha School Nearest), Nandanam, Chennai – 35	Fire extinguishers of DCP 5 Kg type in 4 no's and CO ₂ 2.5 Kg type in 1 no's provided.	1. Down comer system with Hose reel assembly should be provided. 2. Fire extinguishers have to be provided as per IS 2190 for every floor. 3. 450LPM capacity of pump should be provided at terrace level	Non Compliance of Fire Safety Norms.
72.	G. Lakshmi (Late), W/o. Ganeshnan, I st Main Road, C.I.T Nagar, Nandanam, Chennai – 35	NIL	1. Fire extinguishers have to be provided as per IS 2190 for every floor. 2. 450LPM capacity of pump should be provided at terrace level	Non Compliance of Fire Safety Norms.
73.	No.40/22, Karaneeshwarar Koil Street, Saidapet, (Railway Station Opp), Chennai – 15.	NIL	1. Fire extinguishers have to be provided as per IS 2190 for every floor. 2. 450LPM capacity of pump should be provided at terrace level	Non Compliance of Fire Safety Norms.
74.	Kesav Dugar (Apartments) No.1, East Avenue, KesavaPerumalpuram, (Green Wales Road), R.A.Puram, Chennai – 28	Fire extinguishers of DCP 5 Kg type in 10 no's and CO ₂ 4.5 Kg type in 5 no's and ABC 5 Kg type in 5 No's provided.	1. Down comer system with Hose reel assembly should be provided. 2. Fire extinguishers have to be provided as per IS 2190 for every floor. 3. 900 LPM capacity of pump should be provided at terrace level. 4. Manual Call Point should be provided.	Non Compliance of Fire Safety Norms.
75.	Vasantha VIP Apartments, No.3/5, II nd Main Road, Raja Annamalai Puram, Chennai – 600 028.	Fire extinguishers of DCP 5 Kg type in 1 no' and ABC 5 Kg type in 2 no's provided.	1. Hose reel assembly should be provided. 2. 450LPM capacity of pump should be provided at terrace level tank.	Non Compliance of Fire Safety Norms.
76.	Ananthi Apartment, N.No.21, O.No.7, Karaneeswarar Pagoda street, Mylapore, Chennai – 04	NIL	1. Hose reel assembly should be provided. 2. 450LPM capacity of pump should be provided at terrace level tank.	Non Compliance of Fire Safety Norms.
77.	No.7, North Mada Street, Mylapore, Chennai – 04	NIL	1. Down comer system with Hose reel assembly should be provided. 2. Fire Extinguisher should be provided.	Non Compliance of Fire Safety Norms.
78.	West Minister Building, DBS Properties, No.108, Dr.R.K. Salai, Mylapore, Chennai – 04	1. Wet Riser system provided. 2. Manual Call Points provided. 3. Automatic Sprinkler system provided. 4. Automatic smoke detection and fire alarm system provided. 5. Manual call points system provided.	Obstructions in the setback area should be cleared.	Non Compliance of Fire Safety Norms.

		6. Hose Reel system provided.		
79.	No.4, Lady Desika Road, Alwarpet, Chennai – 18	NIL	<ol style="list-style-type: none"> 1. Down comer system with Hose reel assembly should be provided. 2. Fire Extinguisher should be provided as per IS 2190. 3. Sprinkler system should be provided at basement 4. 900 LPM capacity of pump should be provided at terrace level. 5. MCP should be provided. 	Non Compliance of Fire Safety Norms.
80.	No.21A, Adyar Gate Club Road, Ammanane Building, R.A.Puram, Chennai – 28	NIL	<ol style="list-style-type: none"> 1. Down comer system with Hose reel assembly should be provided. 2. Fire Extinguisher should be provided as per IS 2190. 3. 900 LPM capacity of pump should be provided at terrace level. 	Non Compliance of Fire Safety Norms.
81.	No.231, T.T.K Road, Alwarpet, Chennai – 18	NIL	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Yard Hydrant system should be provided. 3. Manual Call Point & Automatic smoke detection and alarm system should be provided. 4. Sprinkler system should be provided. 5. Pump: One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided 	Non Compliance of Fire Safety Norms.
82.	K.G Business Centre, No.65, T.T.K Road, Alwarpet, Chennai – 18	NIL	<ol style="list-style-type: none"> 1. Down comer system with Hose reel assembly should be provided. 2. 900 LPM should be near OH tank. 3. Fire Extinguisher should be provided. 4. Manual Call Point & Automatic smoke detection and alarm system should be provided. 	Non Compliance of Fire Safety Norms.
83.	No.79, No.No.183, T.T.K Road, Alwarpet, Chennai – 18	NIL	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Yard Hydrant system should be provided. 3. Manual Call Point & Automatic Smoke detection and alarm system should be provided. 4. Sprinkler system should be provided. 5. Pumps: One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided 	Non Compliance of Fire Safety Norms.
84.	Raja Rajeswari Tower, No.29/30, Dr.R.K. Salai, Mylapore, Chennai – 04	NIL	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Yard Hydrant system should be provided 3. Manual Call Point with smoke detector should be provided. 4. Sprinkler system should be provided at all floors 	Non Compliance of Fire Safety Norms.

			5. One electrical and a Diesel pump with capacity of 180 LPM and a Jockey pump with capacity of 2280 LPM should be provided	
85.	No.18/12, KesavaPerumal Koil Street, Mylapore, Chennai – 04	NIL	1. Hose reel system should be provided. 2. 450 LPM capacity of fire pump should be provided at terrace level.	Non Compliance of Fire Safety Norms.
86.	Karthick House, No.19, Mandaveli Street, Mandaveli, Chennai – 28	NIL	1. Hose reel system should be provided. 2. 450 LPM capacity of fire pump should be provided at terrace level. 3. Fire extinguishers have to be provided as per IS 2190 for every floor.	Non Compliance of Fire Safety Norms.
87.	O.No.42,43, N.No.85, Kutchery Road, Mylapore, Chennai – 04	NIL	1. Wet riser system with Hose reel assembly should be provided. 2. Manual Call Point & Automatic Smoke detection and alarm system should be provided 3. Pumps: One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided	Non Compliance of Fire Safety Norms.
88.	Rajesh Gupta, N.No.133, O.No.71, Santhome High Road, Chennai – 28	NIL	1. Fire extinguishers have to be provided as per IS 2190.	Non Compliance of Fire Safety Norms.
89.	Prashanth Aparments, No.20, South Mada Street, Mylapore, Chennai – 04	NIL	1. Hose reel system should be provided. 2. 450 LPM capacity of fire pump should be provided at terrace level. 3. Fire extinguishers have to be provided as per IS 2190 for every floor.	Non Compliance of Fire Safety Norms.
90.	N. VenkatRaman Ramaniyam Flats, O.No.25& 26, N.No.2, Srinivasan Street, Mandaveli, Chennai – 28	NIL	1. Hose reel system should be provided. 2. 450 LPM capacity of fire pump should be provided at terrace level. 3. Fire extinguishers have to be provided as per IS 2190 for every floor.	Non Compliance of Fire Safety Norms.
91.	No.4, South Mada Street, Mylapore, Chennai – 04	NIL	1. Hose reel system should be provided. 2. 450 LPM capacity of fire pump should be provided at terrace level. 3. Fire extinguishers have to be provided as per IS 2190 for every floor.	Non Compliance of Fire Safety Norms.

92.	No.265/A, T.T.K Road, Alwarpet, Chennai – 18	<ol style="list-style-type: none"> 1. Down comer system provided. 2. Manual call points provided. 3. Automatic Smoke detection system provided. 4. Automatic Sprinkler system provided. 4. Fire extinguishers have to be provided as per IS 2190 for every floor. 	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Pumps: One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided 	Non Compliance of Fire Safety Norms.
93.	No.107 & 142, Dr. R.K. Salai, VM street, Mylapore, Chennai – 04	NIL	<ol style="list-style-type: none"> 1. Down comer system with Hose reel assembly should be provided. 2. 900 LPM capacity of fire pump should be provided at terrace level. 3. Manual Call Point& Automatic smoke detection and fire alarm system should be provided at office and shop. 	Non Compliance of Fire Safety Norms.
94.	D.No.4, Plot No.10, Lady Desika Road, Mylapore, Chennai – 04	NIL	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Manual call point and Automatic smoke detection and fire alarm system should be provided. 3. One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided 	Non Compliance of Fire Safety Norms.
95.	Moogambi Complex, No.4, Lady Desika Road, Mylapore, Chennai - 04	NIL	<ol style="list-style-type: none"> 1. Wet riser system with Hose reel assembly should be provided. 2. Manual call point and Automatic smoke detection and fire alarm system should be provided. 3. Automatic sprinkler system should be provided. 4. One electrical and a Diesel pump with capacity of 2280 LPM and a Jockey pump with capacity of 180 LPM should be provided 	Non Compliance of Fire Safety Norms.